

- 1. SYSTEMS TEST MISSION FLOWN ON 19 APRIL CONSIDERED MARGINALLY SUCCESSFUL DUE TO FOLLOWING IN-FLIGHT FAILURES:
- A. AS DIRECTED IN REFERENCE, PILOT TURNED SYSTEM 13 TO "STANDBY" FIFTEEN MINUTES AFTER TAKE-OFF. AT TAKE-OFF PLUS 50 MINUTES PILOT SELECTED "RECEIVE" POSITION AT WHICH TIME GREEN LIGHT CAME ON, ONLY TO GO OUT IMMEDIATELY WITH SIMULTANEOUS ILLUMINATION OF "INOP" LIGHT. PILOT WAS UNABLE TO RESET. "INOP" LIGHT STAYED ON FOR REMAINDER OF MISSION. CAUSE OF MALFUNCTION WAS TRAVELING WAVE TUBE FAILURE WHICH IN TURN WAS CAUSED BY A DEFECTIVE HEATER CATHODE TERMINAL INSULATOR IN THE TWT. INSULATOR SHOWED EVIDENCE OF POWER LEAKAGE THROUGH INSULATOR.

B. FAILED TO RECORD DUE TO RECORDER GEAR DRIVE

TRAIN MALADJUSTMENT. UNIT DELIVERED

THIS CONDITION.

P
Approved For Release 2000/0 /14: CIA-RDP71B00263R0002003000 BF-90 CLASSIFICATION

Approved For Release 2000/04/14: CIA-RDP71B00263R000200300087-0

IN 67893 0219)

PAGE 2

25X1A2g

POST FLIGHT INSPECTION OF REVEALED

THAT DRIVE GEARS WERE NOT MESHED, WITH SLIGHT WEAR ON GEAR TEETH TIPS.

- C. SYSTEM 6 APPARENTLY DID NOT OPERATE DUE TO LACK OF D.C. POWEF. MAINTENANCE INVESTIGATION STILL UNDERWAY TO LOCATE BREAK IN CURCUIT, WE ARE PRESENTLY TRACING CIRUITRY.
  - 2. DOPPLER NAV COMPUTER OPERATED AS FOLLOWS:

THE FOUTE INCLUDED THREE 050-270 LEGREE TURNS. DOPPLER SYSTEM APPEARS WITHIN LIMITS.

3. REQUEST THAT PROCEDURAL REVISION OUTLINED IN REFERNCE
BE DELFTED, ALLOWING SYSTEMS TO AGAIN BE TURNED TO "STANDBY" ON
THE GROUND. WE REALIZE THAT SYSTEM OUGHT TO WORK AS OUTLINED
IN REF - BUT WHY CHANGE PROCEDURES THAT HAVE NO RECORD OF MAKING
TROUBLE.

25X1D0b

TOR: 202238ZAPR 67